

## Clamp On Current Transformers – AC



## M3 UB 50A / 1V

AC sensing current transformer designed for use with the PPA range Precision Power Analyzers

## **ELECTRICAL DATA**

Primary rated current Measuring range

Frequency range Output signal

Ratio

Accuracy

Accuracy at 2000 Hz

Phase difference at 2000 Hz

External mini load

Power measurement

Protection class

Dielectric strength

Temperature range

Operating voltage max

"Opening" cable

Dimensions (mm)

Weight

Output connection

Colour

: 50A

: 100mA to 60A

: 40Hz to 5000 Hz

: 1A = 20mV

: 50 / 1

: 1% from 0.1 to 1.2 IN

: 10A at 2%

: 1 degree

: 15 Kohms

: Take care to keep the conventional direction

P1 = S1 rear of the arrows.

: Cat III 600 Volts according to IEC 1010-1

: 3 KV 50 Hz 1 min

: -10° to + 50° C

: 600 Volts

: 15 x 17 mm

: 97 x 43 x 23 mm

: 180 g

: Cable 2 m with insulated BNC

: Blue

Designed in accordance with IEC 1010 - 1

4

**SAFETY WARNING:** This note must be read in full. Any operations on live conductors can be dangerous. The operator is expected to be fully aware of all necessary electrical safety regulations and procedures. Safe operation is his responsibility. It is up to the user to ensure that the equipment is at all times in its original safe conditions.